



# RELEASE NOTES

Firmware revision: 10.14.10

5 October 2023

## Contents

<b>1. General Feature Enhancements .....</b>	<b>2</b>
<b>2. Bugs Addressed .....</b>	<b>2</b>
<b>3. Revision Info .....</b>	<b>2</b>
3.1. Software bundle ONX580.....	2
3.2. ADSL/VDSL Broadcom Modem, B/N ONX580-BDCM-DSL-BONDED .....	2
3.3. VDSL/ADSL Annex A-B Broadcom Modem, B/N ONX-BDCM-DSL-ANXAB .....	3
3.4. ADSL/VDSL/G.fast Broadcom Modem, B/N ONX-TM-BDCM .....	3
3.5. ADSL/VDSL Broadcom/G.fast Sckipio Modem, B/N ONX-TM-GFAST.....	3
3.6. ADSL/VDSL Broadcom 212MHz G.fast Modem, B/N ONX-TM-BDCM-212 .....	3



# RELEASE NOTES

Firmware revision: 10.14.10

5 October 2023

## 1. General Feature Enhancements

### StrataSync

- StrataSync Firmware Enforcement Procedure can now be enabled – motivate techs to upgrade to required firmware by restricting test result uploads and Work Order ID downloads until firmware update is accepted and installed

### Job Manager

- Job Manager Improvement to allow linking selectable Jobs Templates with StrataSync Deployed Job Work Order ID numbers

### OneCheck TDR

- Added AC Volts to the list of metrics displayed and saved in reports

## 2. Bugs Addressed

### Ethernet

- Job ID not present in Fusion Truespeed test report

## 3. Revision Info

### 3.1. Software bundle ONX580.

- Base: 10.14.10
- Access: 10.14.10
- Broadcom 63168 Modem (Annex A Bonded): 001.022.001
- Broadcom 63168 Modem (Annex A/B): 001.022.001
- Broadcom 63138 Modem: 001.019.003
- Broadcom 63158 Modem: 001.012.004
- Sckipio SCK1001 Modem: 005.115.001
- Sckipio SCK23502 Modem: 007.004.006

### 3.2. ADSL/VDSL Broadcom Modem, B/N ONX580-BDCM-DSL-BONDED

- Broadcom 63168 Modem

	Modem SW	Modem PHY
Annex A	4.12L.07.MP.22	A2pv6F039w1.d26k1
Bonded	4.12L.07.BND.22	A2pvbF039x1.d26k1



## RELEASE NOTES

Firmware revision: 10.14.10

5 October 2023

### 3.3. VDSL/ADSL Annex A-B Broadcom Modem, B/N ONX-BDCM-DSL-ANXAB

- Broadcom 63168 Modem

	Modem SW	Modem PHY
Annex A	4.12L.07.MP.22	A2pv6F039w1.d26k1
Annex B	4.12L.07.MPANXB.22	B2pv6F039v.d26k1

### 3.4. ADSL/VDSL/G.fast Broadcom Modem, B/N ONX-TM-BDCM

- Broadcom 63138 Modem

	Modem SW	Modem PHY
Annex A	4.16L.03.GF.19	A2pvfbH045r.d27j
Annex B	4.16L.03.MPANXB.19	B2pvfbH045i.d27j
Bonded	4.16L.03.BND.19	A2pvfbH045r.d27j
G.Fast	4.16L.03.GF.19	A2pvfbH045r.d27j

### 3.5. ADSL/VDSL Broadcom/G.fast Skipio Modem, B/N ONX-TM-GFAST

- Broadcom 63138 & Skipio 1001 Modem

	Modem SW	Modem PHY
Annex A	4.16L.03.GF.19	A2pvfbH045r.d27j
Annex B	4.16L.03.MPANXB.19	B2pvfbH045i.d27j
Bonded	4.16L.03.BND.19	A2pvfbH045r.d27j
Broadcom G.Fast	4.16L.03.GF.19	A2pvfbH045r.d27j
Skipio G.Fast	2.5.115	

### 3.6. ADSL/VDSL Broadcom 212MHz G.fast Modem, B/N ONX-TM-BDCM-212

- Broadcom 63158 Modem

	Modem SW	Modem PHY
Annex A	5.02L.06.MP.12	A2pvfbK046o.d27j
Bonded	5.02L.06.BND.12	A2pvfbK046o.d27j
Broadcom G.Fast	5.02L.06.MP.12	A2pvfbK046o.d27j